


mod. 12/2016 removed FSK from audio

**JUMPERS CONFIG:**



**FIF232**



**DB15-FT-840 Cable**  
FT-840

**S = Sleeve**  
**T = Tip**  
**R = Ring**

**+13.8V**

+13.8V  
RCA

TRX Audio OUT  
S  
T  
**AF OUT**  
RCA

**CAT**

CAT  
MINIDIN6

**KEY**

RADIO KEY  
STEREO 6.3mm (1/4")

MIC  
FOSTER 8